

FIRE SAFETY CERTIFICATE

NO. P-275170

DATE. 13 -02-2026

Certified that the K.D.K INTERNATIONAL SCHOOL at Plot No P-75, R and C Zone , BUTIBORI MIDC,BUTIBORI,NAGPUR-441122 comprised of NIL Basement(s) and Ground Floor and First Floor owned occupied by K.D.K INTERNATIONAL SCHOOL have complied with fire prevention and fire safety requirements in accordance with rule of state/UT fire service Rules, and verified by the officers concerned of Fire Service on Dt.10-02-2026 in the presence of Manager Miss Shraddha Masram , Prasad Colony , Butibori and that the Building / premises is fit for occupancy upto Classes X of Educational Building with effect from Dt.10-02-2026 for a period of ONE YEAR in accordance with rule and subject to compliance of specific conditions.


Issued on Dt.23-02-2026 at Hingana Nagpur



Signature with Seal:-

Name

Designation


Divisional Fire Officer
MIDC, Nagpur-16/02/2026

:- Anand S. Parab

:- Fire Station Officer
MIDC Fire station
Hingana, Nagpur

To,
K.D.K. International School,
Plot No-P-75, R&C Zone, Butibori MIDC, Butibori

Scanned with OKEN Scanner



RENUKA FIRE SERVICES

Head Office: - PT. NO. 33, NEW MANISH NAGAR, PRABHU NAGAR, NAGPUR, 440025

TEL- 9970400222 / 8669157532. E-MAIL - renukafire28@gmail.com

GSTN :- 27CEMPR0159B1Z1

(Maharashtra Government Authorised Fire License Agency)



RFS/Cert-18/06/26-27

FORM - B

See Section 3 (3) and rule 4 (2)

Six Month Certificate to be given in every January and July by the owner of the occupier for compliance of the Fire Prevention and Life Safety Measures.

CERTIFICATE

We **RENUKA FIRE SERVICES** Have Carried Out Inspection of the Fire Prevention and Life Safety measures Installed in the Following Building or Premises Namely-

Company Name & Address :-

M/S K.D.K INTERNATIONAL SCHOOL

**Plot No. 75, R & C Zone, Butibori MIDC, Butibori,
Nagpur-441122**

I /We have Further Certify That These Installations in the Above Mention buildings are maintained in Good Repair and Efficient Conditions during the Period For

01 January 2026 to 30 June 2026 as required under the Provisions of the Maharashtra Fire Prevention and Life Safety Measures Act 2006 (Mah III of 2007) The Details of the Inspection of installations carried out by Me / us are mentioned in the report appended herewith

Place :- Nagpur.

Date :- 18/06/2026

Signature and Address of the Licensed

License No: 2025/RF - 59

License No: 2025/RD - 51

Head Office: - Plot. No. 33, New Manish Nagar, Prabhu Nagar, Somalwada, Nagour, 440025

Br. Office: - Near Agni Railway Ticket Counter, Opp. Ganesh Flower, Agni, Nagpur - 440013

TEL- 9970400222 / 8669157532.

Website: - www.renukafire.in / E-MAIL: - renukafire28@gmail.com



RENUKA FIRE SERVICES

Head Office: - PT. NO. 33, NEW MANISH NAGAR, PRABHU NAGAR, NAGPUR, 440025

TEL- 9970400222 / 8669157532. E-MAIL - renukafire28@gmail.com

GSTN :- 27CEMPR0159B1Z1

(Maharashtra Government Authorised Fire License Agency)



ANNEXURE TO FORM – B

With reference cited above, below is the detail of firefighting system at:

M/S K.D.K INTERNATIONAL SCHOOL

Plot No. 75, R & C Zone, Butibori MIDC, Butibori,
Nagpur-441122

ANNEXTURE FOR FORM - B

Classification of building	EDUCATIONAL BUILDING										
Number Of Floor	G + 1										
Main Electrical Pump	7.5 HP										
Pump Connected With	15000 Ltr(UNDERGROUND)										
Pump Electrical Panel	1										
Wet Riser/Down Comer	Yes Working 100 mm Vertical Riser										
Fire Service Inlet	1										
Fire Alarm Panel 4 Zone	1										
SR. No	List of Equipment	Grnd Floor	1st Floor	2nd Floor	3rd Floor	4th Floor	5th Floor	6th Floor	7th Floor	Total	Status
1	Hydrant Valve	2	2	NA	NA	NA	NA	NA	NA	4	Working Condition
2	Hose Reel Drum	2	2	NA	NA	NA	NA	NA	NA	4	Working Condition
3	Hose Box	2	2	NA	NA	NA	NA	NA	NA	4	Working Condition
4	RRL Hose	2	2	NA	NA	NA	NA	NA	NA	4	Working Condition
5	Short Branch Pipe	2	2	NA	NA	NA	NA	NA	NA	4	Working Condition
6	Sprinkler	NA	NA	NA	NA	NA	NA	NA	NA	NA	Working Condition
7	Fire Extinguisher	2	2	NA	NA	NA	NA	NA	NA	4	Working Condition
8	Manual Call point	2	2	NA	NA	NA	NA	NA	NA	4	Working Condition
9	Hooter	2	2	NA	NA	NA	NA	NA	NA	4	Working Condition
10	Smoke Detector	NA	NA	NA	NA	NA	NA	NA	NA	NA	Working Condition
11	Fire Bucket Stand	1	1	NA	NA	NA	NA	NA	NA	2	Working Condition

Place :- Nagpur.

Date :- 18/06/2026

Signature and Address of the Licensed

License No: 2025/RF - 59

License No: 2025/RD - 51

Head Office: - Plot. No. 33, New Manish Nagar, Prabhu Nagar, Somalwada, Nagour, 440025

Br. Office: - Near Agni Railway Ticket Counter, Opp. Ganesh Flower, Agni, Nagpur - 440013

TEL- 9970400222 / 8669157532.

Website: - www.renukafire.in / E-MAIL: - renukafire28@gmail.com